



5426 Eisenhower Av Alexandria Va 22304 Phone 703-823-9735 Fax 703 823-9737

DATE	
2/27/2020	

BILL TO
Lyons & Sucher 2900 S Quincy St Arlington va 22206 931-2000/ 989-3955 C 931-2088

Car Information	
2007 BMW 335ic 86K P034345 2010 BMW 535i 113K C168807 1974 BMW 2002i	

P.O. NO.	TERMS	REP	SHIP DATE	SHIP VIA	FOB	PROJECT
335i			2/27/2020			

ITEM	DESCRIPTION	QTY	RATE	SERVICED	AMOUNT	
1	Compression test leak down if needed Ran compression test engine cold and hot . Cylinder 1-3-4 are at 145 LBS and # 2 cylinder is at 150 LBS. Averge compression is 135 LBS to 145. Normal cylinder pressure average is 135LBS to 145 LBS This engine compression is on the hi average side. Ran this engine to warm up temps and shows no signs of burning oil or smell.	2			0.00	
2	Check cooling system / heater core, pressure test cooling system and found no issues at engine Cooling or the heater core.	1.5			0.00	
3	Go over car charging system normal all light function with no issues inter heating system work. Raised car over good shape	1	0.00			
Signiture for approval to perform all above services		Thank you for your business		Sales Tax (6.0%) \$0.00		
Warrenty is 24/24 on parts & labor		Balance Due		\$0.00		